

Water infiltration, poor ventilation, or something else?

Mold losses require immediate action.

Mold on the walls and other house surfaces can result from so many things, including improper insulation by the homeowner or contractor, plumbing failure, mechanical failures, code violations, ventilation discharge, and a lot more.

Situations like these need fast remediation before the rest of the structure is affected. Our assessment can locate hidden damage and determine the moisture source causing the mold growth.



Duff White
Certified
Mold
Inspector
for ISE

Duff White is one of ISE's Certified Mold Inspectors who is trained in air and surface sampling, outlining protocol for remediation, and providing a clearance inspection at the end of the work.

For immediate response, call us at 508-226-8800 or email service@iseengineering.com

The
answer is
in the engineering.
15 Extension Street, Attleboro, MA 02703
508-226-8800 Fax: 508-226-8880
service@iseengineering.com



Attic shows well-defined demarcation of mold vs. clean.



IR image of same location shows dramatic temperature variation: a contributing factor for cause of mold.



Bathroom exhaust discharge buried but not connected to exterior of home.



Engineering, Inc.